

METHODS OF APPLICATION :

Surface of preparation : Pass the sandpaper, dust, chew imperfections and let them dry for at least 4 hours. Apply one or two coats of PRIMER AST 100 correctly diluted with an interval of 5 - 4 hours between each application.

APPLICATION :

There are 3 effects proposed for ASTRUM :

STUCCO EFFECT :

Apply a layer of ASTRUM with a stainless steel trowel while making a small movements with the technique of "put and take off" to get the STUCCO EFFECT. Let it dry for 6 hours. Realize polishing and scraping with a trowel and apply one or two coats of CERASTRUM (any color) with an interval of 2 hours.

VENATO EFFECT :

Apply a layer of ASTRUM with a stainless steel trowel while making a vertical movement in to get the VENATO EFFECT. Let it dry for 6 hours. Realize the polishing and the scraping with a trowel, then apply one or two or three layers of CERASTRUM (any color) with an interval of 2 hours.

ASTRATTO EFFECT :

Apply a layer of ASTRUM using an oval tool that is special for ASTRATTO EFFECT. Make circular movements. Let it dry for 6 hours. Realize the polishing and the scraping with a trowel then apply one or two or three layers of CERASTRUM (any color) with an interval of 2 hours.

PACKAGING AND COLOURS :

PRIMER AST 100 : Packaging of 1 - 3 Lt
ASTRUM : Packaging of 5 - 15 Kg
CERASTRUM : Packaging of 0,5 - 1 - 3 Lt

YIELD :

PRIMER AST 1 : 1 Lt → 10 m²
ASTRUM : 1 Kg → 3 m² / 5 Kg → 3 m²
CERASTRUM : 1 Lt → 25 m²

ASTRUM
COLLECTION